

# SAFETY BULLETIN

29 February 2016



## **DINGLI – PRODUCT SAFETY BULLETIN**

The EWPA has been notified by Dingli of a potential stability related issue with their range of Slab Style scissor lifts manufactured before 2014.

Dingli advise that a retrofit solution is being developed that will be applied to affected scissor lift models. Dingli NZ (LiftX Ltd) will issue a notice requesting owners to register with them so that arrangements can be made to have a kit fitted.

Dingli have advised that until the retrofit has been carried out, affected machines should only be operated indoors (i.e. not exposed to wind) and the number of occupants in the platform limited to one person.

Owners of Dingli slab style scissor lifts are advised to contact LiftX Ltd for further information.

**Contact Details:** [office@liftx.co.nz](mailto:office@liftx.co.nz)

Ph: 0800 454 389

[www.liftx.co.nz](http://www.liftx.co.nz)

The Elevating Work Platform Association (EWPA) is the peak Industry Association representing manufacturers, suppliers, rental fleet owners and end users of Mobile Elevating Work Platforms in New Zealand.